



CAMP LEMONNIER



November 19, 2015

- | | | | | | | | | | |
|------------------------|----------------------|--|----------------------|-----------------------|-------------------------|------------------------|----------------------|--|------------|
| | ROUGHNESS_TEST | | Joint Spall, Low | | Small Patch, Medium | | Linear Cracking, Low | | BACKGROUND |
| | adhesion tester | | Popout, High | | Small Patch, Low | | | | SLABS |
| | CORE | | Popout, Medium | | Shrinkage Crack | DISTRESS AREAS | | | |
| DISTRESS POINTS | | | | | | | | | |
| | FOREIGN OBJECT | | Popout, Low | DISTRESS LINES | | | Large Patch, Medium | | |
| | Shattered Slab, High | | Shattered Slab, High | | Linear Cracking, High | | Large Patch, Low | | |
| | Corner Spall, Low | | Small Patch, High | | Linear Cracking, Medium | SLAB QUANDRANTS | | | |

1:141



Sources: Esri, HERE, DeLorme, USGS, Intermap, increment P Corp., NRCAN, Esri Japan, METI, Esri China (Hong Kong), Esri (Thailand), MapmyIndia, © OpenStreetMap contributors, and the GIS User Community